

Cluster Box Unit Accessories

Florence Corporation

5935 Corporate Drive
Manhattan, KS 66503-9675

Telephone: 800-275-1747
785-323-4400

Fax: 800-275-5081 (toll-free)
785-323-4470

florencemailboxes.com

Decorative CBU Accessories
Vogue-Vogue C1, CA-CBUCAP
Vogue-Vogue P114, PA14 Short Pedestal Cover
Vogue-Vogue P128, PA28 Tall Pedestal Cover

CBU accessories are pieces of optional equipment intended to enhance the aesthetic appearance of commercially purchased units.

Salsbury Industries

1010 East 62nd Street
Los Angeles, CA 90001-1598

Telephone: 800-624-5269

Fax: 800-624-5299

mailboxes.com

Decorative CBU Accessories
Regency – 3396, Tall Pedestal Cover
Regency – 3386, Short Pedestal Cover
Regency – 3350, Top Cover, including finial

CBU accessories are pieces of optional equipment intended to enhance the aesthetic appearance of commercially purchased units.

Indoor Parcel Locker

USPS-L-1095G

Salsbury Industries

1010 East 62nd Street
Los Angeles, CA 90001-1598

Telephone: 800-624-5269

Fax: 800-624-5299

mailboxes.com

Unit is powder-coated aluminum in silver and black color scheme to match PO Boxes.

Contract# 3DVDIE-15-B-0092 — Place orders through eBuy2. You must use eBuy2 to purchase supplies from this contract supplier.

Outdoor Parcel Locker (OPL)

USPS-B-1116B

Florence Corporation

5935 Corporate Drive
Manhattan, KS 66503-9675

Telephone: 800-275-1747
785-323-4400

Fax: 800-275-5081 (toll-free)
785-323-4470

florencemailboxes.com

Contract #1CDSEQ-11-B-1004 — Place orders through eBuy2. You must use eBuy2 to purchase supplies from this contract supplier.

Replacement Pedestals — CBU, NDCBU, and OPL Universal

Florence Corporation

5935 Corporate Drive
Manhattan, KS 66503-9675

Telephone: 800-275-1747
785-323-4400

Fax: 800-275-5081 (toll-free)
785-323-4470

florencemailboxes.com

NDCBU Universal Pedestal is anodized aluminum — (Superior PN15825up) (NDCBU PN1582012)

Replacement Pedestal — OPL

Replacement Pedestal — American Locker CBU

Replacement Pedestal — American Locker OPL

Contract #1CDSEQ-11-B-1004 — Place orders through eBuy2. You must use eBuy2 to purchase supplies from this contractor.

Wall-Mounted Centralized Mail Receptacles

USPS-STD-4C

The Postal Service fully implemented USPS-STD-4C on October 6, 2006. All new multi-unit construction with building permits submitted before October 6, 2006, retain the option of using apartment-style receptacles built to the specifications of USPS-STD-4B+.

All multi-unit construction with building plans submitted on October 6, 2006, or later are required to use wall-mounted mail receptacles built and approved to the specifications of USPS-STD-4C.

The receptacles offer:

- Improved compartment security.
- Customer-friendly compartment designs, which allow the carrier to place mail flat into the compartment.
- Increased ease-of-use for carriers.
- Larger customer compartment capacity for small parcels, rolls, and large volumes of mail.
- Ratios of one parcel locker for every 10 customer compartment for installations with 10 customer compartments or more.
- Integral outgoing mail compartments.

The Postal Service primarily intends the use of USPS-STD-4C boxes for new construction and not as a means of retrofitting existing complexes. However, the Postal Service may require buildings undergoing significant renovations or rehabilitations to convert to wall-mounted receptacles that are USPS-STD-4C compliant. If these renovations include significant structural changes and present an opportunity for more complete makeovers, the builders

must include 4C receptacles. The Postal Service does not consider buildings that are simply remodeling or changing the outward/surface appearance of the lobby examples of renovations that would trigger the use of 4C receptacles.

If you have additional questions, contact your area or district growth coordinators for further information, or send an email to wallmountedreceptacles@usps.gov.

Approved Manufacturers

USPS-STD-4C

2BGlobal

895 Dove Street, Suite 300
Newport Beach, CA 92660
Telephone: 800-650-2606
801-808-1118

Fax: 949-502-3772

2B-Globalmailboxes.com

Front Loader Designs

1 and 2 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High) Customer Boxes

Florence Corporation

5935 Corporate Drive
Manhattan, KS 66503-9675
Telephone: 800-275-1747
785-323-4400

Fax: 800-275-5081 (toll-free)
785-323-4470

florencemailboxes.com

Front Loader Designs

Rear Loader Designs

1, 2, 3, 4, and 5 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High) Customer Boxes

Postal Products Unlimited

500 West Oklahoma Avenue
Milwaukee, WI 53207-2649
Telephone: 800-229-4500

mailproducts.com

Front Loader Designs

1 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High) Customer Boxes

Salsbury Industries

1010 East 62nd Street
Los Angeles, CA 90001-1598
Telephone: 800-624-5269

Fax: 800-624-5299

mailboxes.com

Front Loader Designs

Rear Loader Designs

1, 2, 3, and 4 High Customer Compartments

Largest Approved Double-Column Unit has 20 (1 High) Customer Boxes

Apartment House Mail Receptacles — Horizontal and Vertical

The Postal Service has revised USPS-STD-4B. The new standard is USPS-STD-4C. Security-enhanced versions of both horizontal and vertical boxes are now available for replacement of existing equipment. They are referred to as “USPS-STD-4B+” boxes and are designed to fit cleanly into buildings with old USPS-STD-4B boxes.

The Postal Service approves USPS-STD-4B+ boxes for mail delivery for existing indoor installations or existing protected outdoor locations. However, the Postal Service does not approve the purchase of this equipment for new installations and will not install Arrow locks in any such equipment. You may only order *replacement* parts for previously installed Postal Service-owned equipment.

Approved Manufacturers

USPS-STD-4B+

American Eagle Mailboxes

3017 Wheelock Street
Dallas, TX 75220

Telephone: 800-488-4810

Fax: 800-570-0007

americaneaglemailbox.com

Horizontal units only

Florence Corporation

5935 Corporate Drive
Manhattan, KS 66503-9675
Telephone: 800-275-1747
785-323-4400

Fax: 800-275-5081 (toll-free)
785-323-4470

florencemailboxes.com

Salsbury Industries

1010 East 62nd Street
Los Angeles, CA 90001-1598
Telephone: 800-624-5269

Fax: 800-624-5299

mailboxes.com

Locks

PSIN O910A and B, O910HS (per USPS-L-1172D), O913A through K cams, O306P1 (per USPS-L-1294B), O306A1 and A2, O306B and D, O308 (per USPS-K-852H)

CompX Security Products*

PO Box 200
Mauldin, SC 29662-0200

compX.com

*Formerly National Cabinet Lock

Contact: Larry Springgate

Telephone: 864-286-1696

Fax: 864-286-1698

Contract No. 1CDSEQ-11-B-1005

Notes:

1. In accordance with Helping Hand Issue #23, return all nonfunctioning Post Office box locks (PSIN O306B, O306D, O308, O306A1, and O306A2) and excess keys, and Rev. E CBU Parcel Locker Locks (PSIN O306P, see MMO-123-06 and *Postal Bulletin* 22204 (4-12-07, pages 93–94), and reorder using PSIN O306P1) to CompX at the address shown below. This must now include Armor Safe Corporation and Royal Post Office box locks needing replacement keys, which were previously returned to the Mail Equipment Shop.

Lock Refurb Program
CompX Security Products
PO Box 200
Mauldin, SC 29662-0200

2. The preferred method to order locks is from eBay2, Supplier — MDIMSCAT, which is the Topeka Material Distribution Center. Use the following information to order locks:

Material Distribution Center
Attn. Supply Requisitions
500 SW Gary Ormsby Drive
Topeka, KS 66624-9702
email: mdc.customerservice@usps.gov
TTOE: 800-273-1509
Option 1, followed by option 2

Licensing

The U.S. Postal Service licenses two products for sale to customers other than USPS itself: a) customer compartment locks (O910A and B) used in centralized delivery equipment, and b) the CBU, which, when combined with the O910 lock, surpasses a required security level. Commercial manufacturers who wish to become licensed suppliers of either the O910 lock (USPS-L-1172D) or the CBU (USPS-B-1118G) must contact the following office for application procedures:

USPS Licensing Contact

Delivery Team Licensing
3190 South 70th Street, Room 601
Philadelphia, PA 19153-9990

Current CBU Licensees

(See page [11](#).)

Current O910 Lock Licensees

CompX Security Products*
PO Box 200
Mauldin, SC 29662-0200
compX.com

*Formerly National Cabinet Lock

Telephone: 864-286-1696

Fax: 864-286-1698

License Number: 1CDSEQ-08-B-0011

Premium Post Office Boxes**Florence Corporation**

5935 Corporate Drive
Manhattan, KS 66503-9675

Telephone: 800-275-1747
785-323-4400

Fax: 800-275-5081 (toll-free)
785-323-4470

florencemailboxes.com

Place orders through eBay2, eBay PPO-13AF, or PPO-16AF.

This proprietary USPS product uses the CBU platform to make it secure and suitable for outdoor use as an exterior PO Box alternative. Similar to locks used on interior PO Boxes, premium PO Box customer locks are also proprietary USPS products. Premium PO Boxes are available for purchase from the U.S. Postal Service only; they are not available to commercial customers.

Equipment Review Procedure

Employees must use the CBU and parcel locker equipment checklist and follow-up review procedure when examining the condition of CBUs, NDCBUs, and OPLs. You must:

1. List the unit's 5-digit, USPS-marked postal ID number. This is usually visible on the front or side of the body or pedestal. If a postal ID number is not available, list the unit location, equipment type, and manufacturer in the left-hand column. If you are able to access the back of the unit, list the unit's vendor-supplied serial number. You *must* distinguish the type listed as an NDCBU or CBU.
2. Assign each checklist item one of the following ratings:
 - a. OK — Equipment does not need attention for this item.
 - b. X — Equipment needs attention for this item.
 - c. NA — Item does not apply to this particular piece of equipment.
3. When examining the equipment, use the instructions below to complete PS Form 8143:
 - a. Check equipment. All delivery and collection equipment must be straight, vertical, and firmly mounted. For safety concerns, please ensure that customer compartments are facing away from the street or are oriented such that safe collection and delivery of the mail may occur. Visually verify that four bolts/nuts are firmly in place securing the pedestal to the concrete pad and to the delivery equipment. Apply hand pressure to the top edge of the unit from the front side. While the unit may flex under the load, verify that the pedestal stays firmly mounted to the concrete and that the unit does not separate from the pedestal.